OUT57603

1966 JAN 25 00 12 Z

S E C R E T 242349Z

25X1

OXCART

25X1

SUBJECT: EIGHTH PERIODIC SUMMARY REPORT COVERING PERIOD FROM COB 14 JAN 66 THRU COB 21 JAN 66.

STATUS MSN NBR SC&DM DP'S ON'S 12 JAN 66 EVALUATION CONTINUED 65TAØ4 3 DEC 65 12 JAN 66 NO EVALUATION MADE 65TA25 NO PAYLOAD 20 JAN 66 NO EVALUATION MADE 65TA34 20 JAN 66 NO PAYLOAD NO EVALUATION MADE 25 JAN 66 NO PAYLOAD 65TA71 NO EVALUATION MADE 20 JAN 66 NO PAYLOAD 65TA87

66T048 21 JAN 66

25 JAN 1966

65TAØ4 - DURING CAMERA OPERATION THERE ARE ELAPSED TIME JUMPS ON INS TAPE OTHER THAN 4. 5. OR 6 SECONDS. THERE ARE SEVERAL NINE SECOND JUMPS (E.G. ELAPSED TIME 3892 - 3901; 3901 - 3910), ADMIN SEC BR AND ONE 14 SECOND JUMP (8613 - 8627). IT IS ASSUMED IN THE CORRELA-P & DS CSD TION TO FILM THAT ONE LINE OF DATA HAS BEEN OMITTED OR LOST FOR IPD PO THE 9 SECOND JUMP AND 2 LINE FOR THE 14 SECOND JUMP. ALSO THERE **PSD** PSD-ICB WERE ELAPSED TIME DIFERENCES OF 1, 2, AND 3 SECONDS. FOR THE TA TID IAD TO FILM CORRELATION THESE LINES WERE OMITTED. IN THIS MANNER PAG THE NUMBER OF LINES OF INS DATA AND THE NUMBER OF FORWARD CAMERA DIAXX-4 FRAMES OF PHOTOGRAPHY WERE QUITE CLOSE. FOR EXAMPLE, UP TO THE FIRST NEA-LO DIA-AP CAMERA OFF (FRAME 238), THERE WAS ONE MORE FORWARD FRAME OF PHOTO-

Advange copy

SECRE

GRAPHY THAN INS DATA. THIS, HOWEVER, PRESENTS THE PROBLEM OF INSERTING A LINE IN THE 9 SECOND INTERVAL, TO MAKE A 4 SECOND AND A 5 SECOND DIFFERENCE.

THE FIRST GOOD LINE OF DATA ON THE INS TAPE READS ELAPSED TIME 3755. THE GMT TIME WHEN INS ENTERED NAV MODE ON INS HEADER IS 163525. THE DATA BLOCK CLOCK TIME READING FOR FRAME ONE IS 193807. THIS CONVERTS TO AN ELAPSED TIME OF 10962. AN EXACT TIME CORRELATION OF TAPE TO FILM COULD NOT BE MADE BECAUSE OF THE INABILITY TO RESOLVE DISCREPANCY IN ELAPSED TIMES.

EVALUATION HAS BEEN COMPLETED TO THE FIRST CAMERA OFF AT FRAME 238 APPROXIMATE ELAPSED TIME 4285. THE FILM DATA BLOCK LATITUDE LED THE INS LATITUDE IN THE DIRECTION OF FLIGHT BY 4 TO 5 MINUTES. THE FILM DATA BLOCK LONGITUDE LED THE INS LONGITUDE IN THE DIRECTION OF FLIGHT BY 1 TO 2 MINUTES.

ERRONEOUS DATA APPEARS TO HAVE BEEN GIVEN IN THE INS TAPE LONGITUDE COLUMN AT ELAPSED TIME 9321 AND 9741.

SUGGEST 11180 FOR 11170 AND 11618 FOR 11698 RESPECTIVELY.

TAPE TO FILM CORRELATION 50 PERCENT COMPLETE.

SECRET

/END OF MESSAGE/